

## EXPERTool Release Note (2019/10/1)

### V10.32

Fix LED issue

Fix "Restore Fan#2 auto" issue

### V10.31

Fix "RTX series LED issue"

### V10.3

Adding "Restore" LED settings (default: GPU temperature)

### V10.29

Update save BIOS function (nvflash v5.567.0)

### V10.28

Minor bug fixed for O.C. dialog refresh

### V10.27

Update save BIOS function (nvflash v5.560.0)

### V10.26

Fix minor bug of "saving BIOS" function

Fix "LED breath mode" function

### V10.25

Update save BIOS function (nvflash v5.558.0)

### V10.24

Update save BIOS function (nvflash v5.557.0)

### V10.23

Update save BIOS function (nvflash v5.556.0)

Update "GPU OC SCAN" for GeForce RTX 20/GTX 16 series

Update LED control function

Support only 64bits OS

### V10.22

Update save BIOS function (nvflash v5.541.0)

Update "GPU OC SCAN" v1.1.0

#### V10.21

Update save BIOS function (nvflash v5.531.0)

Support "GPU OC SCAN" for GeForce RTX 20 series

#### V10.2

Update save BIOS function (nvflash v5.527.0)

Support GeForce RTX 20 series and others with R415 driver (v416.34) or newer

#### V10.12 (beta)

Update save BIOS function (nvflash v5.519.0)

Support GeForce RTX 20 series only

#### V10.10

Update save BIOS function (nvflash v5.469.0)

#### V10.9

Update save BIOS function (nvflash v5.449.0)

#### V10.8

Fixed GTX 1060 5GB issue with new driver (R390)

#### V10.7

Update save BIOS function (nvflash v5.427.0) to support GTX 1060 5GB

#### V10.6

Add GTX 1070 Ti STD edition in OC/Gaming/Silence mode support list

#### V10.4

Update save BIOS function (nvflash v5.412.0) to support GTX 1070 Ti

#### V10.3

Fix P106-100/P104-100 detecting issue.

#### V10.2

1. Update NVAPI R384

2. Update save BIOS function (nvflash v5.398.0)
3. Added a dialog message to indicate when 'debug mode' option enabled in NV control panel

#### V10.1

Support 8 GPUs

#### V10.0

1. Add OC/Gaming/Silence mode tooltip
2. Fix reload OC/Gaming/Silence mode on startup
3. Reduce application size

#### V9.27

1. Add OC/Gaming/Silence mode (GTX 1080 Ti only)
2. Update save BIOS function (nvflash v5.370.0)

#### V9.26

Update save BIOS function (nvflash v5.367.0) to support GTX 1080 Ti

#### V9.25

1. Update save BIOS function (nvflash v5.353.0)
2. Fix status fan curve (fan line response incorrectly)

#### V9.24

1. Support 6 GPUs
2. Update save BIOS function (nvflash v5.328.0) to support GTX 1060 GP104-140 GPU
3. Fix user mode save issue (can't save fan setting)

#### V9.23

Update save BIOS function (nvflash v5.323.0) to support GTX 1050 Ti

#### V9.22

Fix LED control issue (some customer report LED button disappear)

Update save BIOS function to support GTX 1060 3GB

Adjust STATUS core clock scale range

#### V9.21

Fix LED control issue (settings being reset if close the LED control page)

Add Temperature target control.

Fix GPU over voltage setting unsaved.

Update save BIOS function to support GTX 1060 6GB

V9.20

Fix LED control issue (settings being reset if close the LED control page)